

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041200

8/12/2026
4:29 pm

2005 BMW X5
V8-4398 4.4L DOHC
VIN : 5UXFB53585LV13655
Mileage :
Trans : AUTO
License : DEALER
COLR : SILVER

DJPJ HOLDINGS
14635 HAGUS PL
PARKER, CO 80134
MOBILE:(734) 395-5097
WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Service Requests:

Category Summary	Parts	Labor	Job Total
ABS SYSTEM	\$37.06	\$97.78	\$134.84
BODY	\$93.18	\$0.00	\$93.18
CHARGING SYS & BATT	\$232.86	\$78.22	\$311.08
COOLING SYSTEM	\$82.46	\$97.78	\$180.24
DRIVE TRAIN	\$80.50	\$831.11	\$706.50
ELECTRICAL	\$69.04	\$0.00	\$69.04
ENGINE	\$342.38	\$97.78	\$317.29
LAMPS & BULBS	\$46.33	\$97.78	\$81.17
TRANSFER CASE	\$211.06	\$488.89	\$699.95
WHEEL BEARING	\$110.92	\$309.76	\$420.68
WINDSHIELD WIPER	\$38.12	\$58.67	\$62.95

Technician	Service Description	Parts	Labor	Job Total
TK	DIAGNOSE CRANK BUT NO START CONDITION - Timing	25.09	97.78	122.87
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-254230 AXLE OUTPUT SHAFT SE	25.09	1	25.09
TK	REPLACE BATTERY	232.86	78.22	311.08
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
S	985 BATTERY TERMINAL PROTECTORS	5.50	1	5.50
N	H8DLG 36 MONTH WET BATTERY	206.66	1	206.66
N	3374650 246239 DUAL CLUTCH TRANS FL	20.70	1	20.70
TK	INSPECT FOR ENGINE TIMING ISSUE	317.29	0.00	317.29
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-333647 CAMSHAFT SOLENOID GA	3.50	4	14.00
N	WP-333648 CAMSHAFT SOLENOID GA	0.48	4	1.92
N	1802-684001 VAR. VALVE LIFT ECCT	190.07	1	190.07
N	WP-338022 BREATHER HOSE VENT P	42.90	1	42.90
N	WP-338023 BREATHER HOSE VENT P	68.40	1	68.40
TK	REPLACE LEFT HALO BULB	32.28	48.89	81.17
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-308374 DAYTIME RUNNING LIGH	32.28	1	32.28
TK	REPLACED LEAKING WASHER PUMP GROUMETS FOR WINDSHIELD AND REAR GLASS PUMPS	14.06	48.89	62.95
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-235228 WINDSHIELD WASHER PU	7.03	2	14.06
TK	REPLACE BROKEN COOLANT HOSE	82.46	97.78	180.24
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-278674 EXPANSION TANK HOSE	68.26	1	68.26
S	0020 COOLANT GOLD PLUS EXT LIFE	7.10	2	14.20
TK	FRONT 75W-90 SYN DIFFERENTIAL SERVICE: DRAIN AND REFILL FRONT DIFFERENTIAL FLUID WITH 75W-90 SYNTHETIC FLUID	9.54	48.89	58.43
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
S	04803 75W-90 SYN SYNTH GEAR OIL QT.	9.54	1	9.54
TK	REAR 75W-90 SYN DIFFERENTIAL SERVICE: DRAIN AND REFILL REAR DIFFERENTIAL FLUID WITH 75W-90 SYNTHETIC FLUID. INSTALL MGC GEAR OIL ADDITIVE	28.62	48.89	77.51
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
S	04803 75W-90 SYN SYNTH GEAR OIL QT.	9.54	3	28.62
TK	TRANSFER CASE DRAIN & FILL TRANSFER CASE	20.28	48.89	69.17
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	3374650 246239 DUAL CLUTCH TRANS FL	20.28	1	20.28
TK	REPLACE WINDSHIELD WIPERS	24.06	9.78	33.84
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	40 722A WINDOW WIPER BLADE M	9.91	1	9.91
N	40 724 WINDOW WIPER BLADE M	14.15	1	14.15
TK	REPLACE SIDEMARKR BULB	7.16	48.89	56.05
	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			



Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041200

8/12/2026
4:29 pm

2005 BMW X5
V8-4398 4.4L DOHC
VIN : 5UXFB53585LV13655
Mileage :
Trans : AUTO
License : DEALER
COLR : SILVER

DJPJ HOLDINGS
14635 HAGUS PL
PARKER, CO 80134
MOBILE:(734) 395-5097
WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Technician	Service Description	Parts	Labor	Job Total
N	3457A BULB MINIATURE HALOG	3.58 2 7.16		
TK	REPLACE BOTH FRONT OUTER CV BOOTS	22.06	684.44	706.50
N	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-177992 CV BOOT KIT W/ CLAMP	11.03 2 22.06		
TK	REPLACE FOG LIGHT BULB	6.89	0.00	6.89
N	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	BLBH1155WLL HEADLIGHT BULB LONG	6.89 1 6.89		
TK	REPLACE LEFT, FRONT, CENTER PARKING SENSOR	69.04	0.00	69.04
N	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-425743 PARKING AID SENSOR I	69.04 1 69.04		
TK	REPLACE FRONT RIGHT DOOR HANDLE HOUSING	93.18	0.00	93.18
N	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	WP-329917 OUTSIDE DOOR HANDLE	78.06 1 78.06		
N	WP-378491 DOOR PANEL CLIP GRAY	1.26 12 15.12		
TK	REPLACE ABS SENSOR IN REAR	37.06	97.78	134.84
N	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	1802-300910 ABS SPEED SENSOR SER	37.06 1 37.06		
TK	REPLACE BOTH REAR WHEEL BEARINGS	110.92	309.76	420.68
N	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	DL512226 REAR WHEEL BEARING	55.46 2 110.92		
TK	TRANSFER CASE LABOR	211.06	488.89	699.95
N	<u>Part Number</u> <u>Part Description</u> <u>Part Price Each</u> <u>Quantity</u> <u>Extended</u>			
N	ATC500 TRANS CASE CLUTCH KIT - EBAY	106.64 1 106.64		
N	3374650 246239 DUAL CLUTCH TRANS FL	20.70 2 41.40		
N	WP-254228 INPUT SHAFT SEAL 49.	28.33 1 28.33		
N	SP00445 TRANS CASE INPUT SFT	6.19 1 6.19		
N	WP-686985 DIFF. SIDE COVER O-R	3.00 1 3.00		
N	WP-254228 INPUT SHAFT SEAL 49.	25.50 1 25.50		

Authorizations

Approved By:	Approval Given To:	Date	Time	Difference	Total Authorized	Method
DJ		6/5/26	4:01 pm	\$2,693.50	\$2,693.50	By Phone
Reason:						

Repair Order Notes



Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041200**8/12/2026
4:29 pm****2005 BMW X5**

V8-4398 4.4L DOHC
VIN : 5UXFB53585LV13655

Mileage :
Trans : AUTO
License : DEALER

COLR : SILVER

DJPJ HOLDINGS

14635 HAGUS PL
PARKER, CO 80134
MOBILE:(734) 395-5097
WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Technician Service Description

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage or articles left in vehicle theft or any other cause beyond our control.

WARRANTY IS 12 MONTHS OR 12,000 MILES WHICH EVER OCCURS FIRST, UNLESS OTHERWISE SPECIFIED. A SERVICE CHARGE WILL BE APPLIED FOR ALL CARD PURCHASES.

Customer Signature: _____ Date: _____

Parts Labor Job Total

TOTAL PARTS	\$1,343.91
TOTAL LABOR	\$2,157.77
SUBLET	\$0.00
SHOP SUPPLY	\$0.00
SUBTOTAL	\$3,501.68
OTHER FEES	\$0.00
SALES TAX	\$90.71
INVOICE TOTAL	\$3,592.39
PAID	\$0.00
DUE	\$3,592.39

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE:

**Thank you for your business!**